

00862.002789



PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

HIROKI HIYAMA ET AL.

Appln. No.: 09/291,006

Filed: April 14, 1999

For: SOLID-STATE IMAGE SENSING
APPARATUS AND METHOD OF
OPERATING THE SAME

U.S. Patent No.: 6,963,372 B1

Issued: November 8, 2005

) Examiner: James M. Hannett

) Group Art Unit: 2612

) :

) :

) :

) :

) February 22, 2006

Certificate

FEB 28 2006

of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

FER 28 2006

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



John A. Krause
Attorney for Patentees
Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200
553724V1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,963,372 B1

DATED : November 8, 2005

INVENTOR(S) : HIROKI HIYAMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 5-18309 3/1983" should read --JP 5-18309 3/1993--; and
"JP 4-61573 2/1992" should be deleted.

COLUMN 2

Line 42, "t^{35p}," should read --t_{35p}--.

COLUMN

Line 29, "drop" should read --drop of--.

COLUMN 9

Line 45, "t₂₅₁" should read --t₂₅--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,963,372 B1

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,963,372 B1

DATED : November 8, 2005

INVENTOR(S) : HIROKI HIYAMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 5-18309 3/1983" should read --JP 5-18309 3/1993--; and
"JP 4-61573 2/1992" should be deleted.

COLUMN 2

Line 42, "t^{35p}," should read --t_{35p}--.

COLUMN

Line 29, "drop" should read --drop of--;

COLUMN 9

Line 45, "t₂₅₁" should read --t₂₅--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 6,963,372 B1

No. of add'l. copies
@ 30¢ per page

